

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1344  
East  
> 1  
1.707 mi.  
9015 ft.

174 FALMOUTH STREET  
174 FALMOUTH STREET  
BROOKLYN, NY

NY LTANKS  
NY Spills  
S104646730  
N/A

Relative:  
Higher

Actual:  
3 ft.

LTANKS:

Name: 174 FALMOUTH STREET  
Address: 174 FALMOUTH STREET  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9210975 / 1992-12-22  
Facility ID: 9210975  
Site ID: 78352  
Spill Date: 1992-12-22  
Spill Cause: Tank Overfill  
Spill Source: Private Dwelling  
Spill Class: C3  
Cleanup Ceased: 1992-12-22  
SWIS: 2401  
Investigator: CAMMISA  
Referred To: Not reported  
Reported to Dept: 1992-12-22  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Responsible Party  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: True  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 1992-12-22  
Spill Record Last Update: 2004-09-30  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller County: 001  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 72919  
DEC Memo: ""  
Remarks: "DRIVER MIS-READ TANK CHART-OIL LEAKED FROM FILL PIPE TO SIDEWALK  
AREA-DRIVER APPLIED SORBENTS SPILL TEAM ENROUTE TO COMPLETE CLEANUP"

All Materials:

Site ID: 78352  
Operable Unit ID: 975269  
Operable Unit: 01  
Material ID: 404410  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 5.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

SPILLS:

Name: 174 FALMOUTH STREET  
Address: 174 FALMOUTH STREET  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9210985 / 1992-12-22  
Facility ID: 9210985  
Facility Type: ER  
DER Facility ID: 72919  
Site ID: 78353  
DEC Region: 2  
Spill Cause: Human Error  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1992-12-22  
Investigator: CAMMISA  
Referred To: Not reported  
Reported to Dept: 1992-12-22  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Tank Truck  
Spill Notifier: Responsible Party  
Cleanup Ceased: 1992-12-22  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1992-12-23  
Spill Record Last Update: 2004-09-30  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: ""  
Remarks: "SPILL ON SIDEWALK-CLEANED UP W/ SPEEDI-DRI"

All Materials:

Site ID: 78353  
Operable Unit ID: 975277  
Operable Unit: 01  
Material ID: 404420  
Material Code: 0001A  
Material Name: #2 fuel oil  
  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 5.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: SPILL NUMBER 9713283  
Address: 174 FALMOUTH STREET  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9713283 / 2003-02-19  
Facility ID: 9713283  
Facility Type: ER  
DER Facility ID: 72919  
Site ID: 201717

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

DEC Region: 2  
Spill Cause: Human Error  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1998-02-26  
Investigator: KGHale  
Referred To: Not reported  
Reported to Dept: 1998-02-27  
CID: 281  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1998-02-27  
Spill Record Last Update: 2003-02-19  
Spiller Name: PAUL SCAROLA  
Spiller Company: PETRO OIL  
Spiller Address: 55-61 58TH  
Spiller Company: 001  
Contact Name: MR SLIFMAIN  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
HALE 2/19/2003 - Closed Due To The Nature / Extent Of The Spill  
Report"  
Remarks: "BACK PRESSURE IN VENT LINE UPON DELIVERY OF MATERIAL. MATERIAL WILL  
BE CLEANED UP TOMMORROW BY RESPONSIBLE PARTY."  
All Materials:  
Site ID: 201717  
Operable Unit ID: 1056167  
Operable Unit: 01  
Material ID: 324303  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported